

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

323  
SSW  
1/2-1  
0.513 mi.  
2709 ft.

PAINT DRUMS  
CONEY IS. RECREATION AREA  
BROOKLYN, NY

NY Spills S102143924  
N/A

Relative:  
Higher

Actual:  
9 ft.

SPILLS:

Name: PAINT DRUMS  
Address: CONEY IS. RECREATION AREA  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 8600231 / 1986-04-02  
Facility ID: 8600231  
Facility Type: ER  
DER Facility ID: 140857  
Site ID: 167193  
DEC Region: 2  
Spill Cause: Deliberate  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 1986-04-02  
Investigator: UNASSIGNED  
Referred To: Not reported  
Reported to Dept: 1986-04-09  
CID: Not reported  
Water Affected: NONE  
Spill Source: Commercial/Industrial  
Spill Notifier: Local Agency  
Cleanup Ceased: 1986-04-02  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1986-05-27  
Spill Record Last Update: 1986-06-26  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
  
Spiller Company: 999  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "  
Remarks: "ACT. QUAN. SPILL-50 DRUMS-SUSPECT DUMPING-NYC DEP IS HIRING CONTRACTOR TO CLEANUP"

All Materials:

Site ID: 167193  
Operable Unit ID: 896482  
Operable Unit: 01  
Material ID: 480401  
Material Code: 0630A  
Material Name: nonene  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported

Site ID: 167193  
Operable Unit ID: 896482

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit: 01  
Material ID: 480400  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported